

Oil Field Environmental Incident Summary

Incident: 20130725120032 **Date/Time of Notice:** 07/25/2013 11:00

Responsible Party: Resolute Natural Resources Company, LLC

Well Operator: RESOLUTE NATURAL RESOURCES COMPANY, LLC

Well Name: FOREST USA 14-2H

Field Name: LONE BUTTE

Well File #: 19718

Date Incident: 7/24/2013 **Time Incident:** 21:30

Facility ID Number:

County: MCKENZIE

Twp: 147

Rng: 98

Sec: 2

Qtr: SW SW

Location Description:

Submitted By: Mike McKee

Received By:

Contact Person: Mike McKee
1675 BROADWAY, SUITE 1950
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Free standing oil in flare pit.

Areal Extent:

Potential Environmental Impacts:

Impacts are to surficial soils within flare pit and oil misting to surficial soils and vegetation immediately adjacent to flare pit.

Action Taken or Planned:

Free standing oil is contained within flare pit and vacuum truck will remove all free standing oil and transfer back to oil tanks. Affected surficial soils within the flare pit will be scraped and removed from site. Misting impacts will be evaluated and any impacted surficial soils and/or vegetation will be removed, if necessary.

Wastes Disposal Location: Petroleum-impacted material will be transferred to Indian Hills Disposal in Williston.

Agencies Involved: USDA-Forest Service

Updates

Date: 7/25/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the location listed within the report the site is on USFS land. Release was contained within the system dikes. USFS lead.